






Phase Diagram of a Pure Substance

Three-Dimensional Surface and
Two-Dimensional Projections





Pressure-Temperature and Pressure-Volume Projections for a Typical Pure Substance



**Pressure-Temperature and Pressure-Volume Projections
Showing Several Different Isotherms**